



CIMS INTERNATIONAL N.V.

Container, cargo & marine surveyors


ON HIRE/CONDITION INSPECTION REPORT

CONTAINER NUMBER		CLIENT NAME		SURVEY DATE		LOCATION		DEPOT	
GAS 111010.3		Tanspa		23/4/01		Rykm.		Dami	
TANK TYPE	MANUFACTURER	SERIAL NO.	ISO TYPE		TANK	MAX	PAYLOAD	TARE	
IMU1	WD.	15749	7216		21030			3360	
FIRST TEST	LAST 2 1/2 YR TEST	LAST 5 YR TEST	NEXT TEST DUE		CSC	MAWP	TEST		
11/00.					11/05				
STWP	ST PRESS.	TANK HEAD MAT		TANK SHELL MAT		HEAD THICKNESS	SHELL THICKNESS		

GENERAL CONDITION FRAME:

CLADDING:

PAINT:



DAMAGE CODES

- B Bent C Cut D Dent CR Cracked EZ Exst. Rep. H Hole
- COR Corrosion L Loose SC Scratched M Missing ST Stained IR Improper Repair

COMPONENT CHECK LIST	FITTED		COMMENTS
	Y	N	
MARKINGS AND PLATES			
Data plates	✓		
Owners plate	✓		
Manufacturer's plate	✓		
CSC plate	✓		
Custom approval plate	✓		
Prefix number	✓		
IMO/DOT E number	✓		
Country code	✓		
Owner label	✓		
AAR 600	✓		
CTC impact approval	✓		
Weight / volume decals	✓		

INTERNAL INSPECTION REPORT


TANK SERIAL NO. SASL 111010.3 LAST PRODUCT:

Location: Ref. No.

Inspected By: Order No.


Date:

FRONT



	12	11	10	9	8	7	6	5	4	3	2	1	
A													A
B													B
C													C
D													D
E													E
F													F
G													G
H													H

To wipe out
clear



REAR

SURFACE CONDITION

- STAINING
- SURFACE RUST
- SURFACE SCORING
(Scratch/gouge marks)
- PITTING

INDICATE TYPE & SHAPE
See Note II of Section 9 on Corrosion
Pitting in ACC.

DRAW PITTING TYPE
or indicate A,B or C.

DRAW PITTING SURFACE SHAPE
(Circular, elongated, etc.)

Pitting depth Average mm/inch
Pitting depth Maximum mm/inch

Area of shell affected %

Pitting in weld bead Y/N

Is pitting light or heavy L/H

Pitting in heat zone of weld bead Y/N

Is pitting light or heavy L/H

If tank is stained indicate colour

Condition of syphon tube

Indicate weld seam in plan

ADDITIONAL COMMENTS


Name (Print) Signed *[Signature]* Date

TANK CONTAINER NO. : Gen 111010.3

COMPONENT CHECK LIST	FITTED		COMMENTS
	Y	N	
EXTERNAL ACCESSORIES			
Front ladder		✓	
Rear ladder	✓		
Document, Box/Cap/Gask/Chain	✓		
Outlet Cap/Blank/Gask/Chain	✓		Size <u>3"</u> <u>ALU/SS</u>
Bottom outlet valve/gaskets	✓		MFR <u>FV</u> <u>Butterfly/Ball</u>
Footvalve	✓		MFR <u>FV</u>
Remote footvalve control	✓		
Steam Tubes/Cap/Gask/Chain	✓		Size <u>3/4"</u> <u>ALU/SS</u> <u>pvc</u>
Thermometer	✓		MFR <u>wika</u> <u>(C-F)</u>
Walkway	✓		
Manhole Protection Cover		✓	
Spillbox	✓		
Manlid / Seal	✓		<u>SWR/PTFE</u>
Manlid swing bolts	✓		<u>4-6-8</u> Bolted
Dipstick	✓		
Calibration Chart	✓		
Safety Dev. Prot. Cover/Spillbox	✓		
EXTERNAL ACCESSORIES			
P/V Relief valves 1	✓		MFR <u>FV</u> Ser <u>12293</u> Vac <u>No</u> Press ✓
P/V Relief valves 2		✓	MFR <u>FV</u> Ser _____ Vac _____ Press _____
Pressure Gauges		✓	MFR _____ Range _____
Flame Traps on P/V Rel. Val.	✓		
Air Line Cap/Gasket/Blank/CH	✓		Size <u>1 1/2"</u> <u>ALU/SS</u>
Air Line Valve/Gasket/Gauge	✓		MFR _____ Range _____
Top Disch. Prot. Cover/Spillb.	✓		
Top Disch. Valve		✓	MFR _____ Butterfly/Ball
Top Disch. Blank/Gas.	✓		
Top Operated Int. Footvalve		✓	
Tir strips bottom/top	✓		
INTERNAL CONDITION			
Cleaned / Dry	✓		<u>Ins to wipe out</u>
Discoloured		✓	<u>see mapping</u>
Rusted		✓	
Corroded		✓	
Pitted/Lamination Pitting		✓	
Thermometer probe		✓	
Valv. Clean fr. Moist/Res.	✓		
Siphon tube		✓	
Footvalve	✓		
Bursting discs		✓	MFR _____ Range _____
Cleanliness certificate	✓		

REMARKS : Inside to wipe out

<input checked="" type="checkbox"/> Accepted	Surveyor's Name <u>[Signature]</u>
<input type="checkbox"/> Rejected	



INTERNATIONAL (HOLLAND)

Container, cargo & marine-surveyors

Langs de baan 110, 3191 TP Rotterdam-Hoogvliet

Telephone: (0)10 - 472 01 22/416 48 82 Telex: 28403 Fax (0)10 - 416 47 51

To whom it may concern

TANK CONTAINER INSPECTION REPORT

The above company has surveyed the following tank container and inspected it for cleanliness.

Container no.: 4224 111010.3 Tank type: TRUO
 Premises : Deni
 Last product : NEW TALL
 Date and time of inspection: 23rd April 2001 at 10¹⁰ hrs

SAFE FOR MEN	YES / NO
SAFE FOR FIRE	YES / NO
DRY	YES / NO
ODOURLESS	YES / NO
SHELL SURFACE CLEAN (visual examination only)	YES / NO
MANHOLE GASKET CLEAN	YES / NO
TOP DISCHARGE VALVE / SYPHON TUBE CLEAN	YES / NO
BOTTOM DISCHARGE VALVE CLEAN	YES / NO
ALCOHOL TEST 6 POINTS PERFORMED (FOODSTUFF ONLY)	YES / NO
OXYGEN CONTENT	<u>21%</u>

The container is inspected for transport of: _____

Sealno.: _____

This report refers to the condition of the tank container at the time of inspection only.

NAME OF INSPECTOR: [Signature] **C.I.M.S. International (Holland)**

ABN-AMRO Bank - account no. 42.60.42.638
K.v.K. Rotterdam H.reg. no. 134209



INTERNATIONAL N.V. - Rotterdam office

Container, cargo & marine-surveyors

Langs de baan 110, 3191 TP Rotterdam-Hoogvliet

Telephone: (0)10 - 416 48 82/472 01 22 Telex: 28403 Fax (0)10 - 416 47 51

TO WHOM IT MAY CONCERN

=====

TANK NUMBER : Gasn. 111010.3

LOCATION : Den i

IM CODE : IM 101

LAST TEST DATE : 12/00

WE HEREBY DECLARE THAT DURING OUR PRESSURE-TEST INSPECTION TANK IS PUT UNDER 1 BAR AIRPRESSURE AND PROVEN TO BE AIRTIGHT FOR ALL SEALS.

SIGNED BY INSPECTOR CIMS : 

INSPECTION DATE : 23/4/01

Bankers: Amro-Bank
Hfl. acc. no. 4877 69481
\$ acc. no. 4877 69775









